

# Oil Field Environmental Incident Summary

**Incident:** 20141013100523      **Date/Time of Notice:** 10/13/2014 10:05

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** NESS 44-21H CTB

**Field Name:** SANISH

**Well File #:**

**Date Incident:** 10/12/2014      **Time Incident:** 11:00      **Facility ID Number:** 218244-01

**County:** MOUNTRAIL      **Twp:** 154      **Rng:** 91      **Sec:** 21      **Qtr:** SE SE

**Location Description:**

**Submitted By:** Brian Wurm

**Received By:**

**Contact Person:** Brian Wurm  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	70	Barrels	70	Barrels	70	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 11/14/2014      **Clean Up Concluded:** 10/14/2014

**Risk Evaluation:**

None noted

**Areal Extent:**

**Potential Environmental Impacts:**

None noted

**Action Taken or Planned:**

Flow to the treater was switched to stop the release of fluids. A vac truck was brought in and picked up all free liquids and impacted material. The treater will not be brought back into service until the fire tube leak is addressed.

**Wastes Disposal Location:** Recovered fluids will be returned to production tanks on location and impacted material will be taken to appropriate landfill.

**Agencies Involved:**

**Updates**

---

**Date:** 10/14/2014 **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a treater leak, remained on location within the diking according to the report. NDIC retains oversight.